

SUBJECT

SPECIFICATION REFERENCE

WITH DRAW FEB '72

DATE CODE

P 50X - 1
Sheet 1

FOR LAMP MARKING AND LABELLING

DATE

April 1946

The following date code must be used for the marking of lamps and the labelling of containers where specified in the relevant marking or labelling specification.

Month	1946	1947	1948	1949
January	49	61	73	85
February	50	62	74	86
March	51	63	75	87
April	52	64	76	88
May	53	65	77	89
June	54	66	78	90
July	55	67	79	91
August	56	68	80	92
September	57	69	81	93
October	58	70	82	94
November	59	71	83	95
December	60	72	84	96

OSRAM-G.E.C. LAMP AND METALS FACTORIES

SUBJECT

WITH DRAW FEB '72

DATE CODES
FOR LAMP MARKING & LABELLING

SPECIFICATION REFERENCE

PSCA-2
Sheet 2

DATE

MARCH 1970

ISSUE

The following date code must be used for the marking of lamps and the labelling of containers where specified in the relevant marking or labelling specification.

	1950	1951	1952	1953	1954	1955	1956	1957
JANUARY	01	13	25	37	49	61	73	85
FEBRUARY	02	14	26	38	50	62	74	86
MARCH	03	15	27	39	51	63	75	87
APRIL	04	16	28	40	52	64	76	88
MAY	05	17	29	41	53	65	77	89
JUNE	06	18	30	42	54	66	78	90
JULY	07	19	31	43	55	67	79	91
AUGUST	08	20	32	44	56	68	80	92
SEPTEMBER	09	21	33	45	57	69	81	93
OCTOBER	10	22	34	46	58	70	82	94
NOVEMBER	11	23	35	47	59	71	83	95
DECEMBER	12	24	36	48	60	72	84	96

CONFIDENTIAL

The information on this sheet is the property of Osram-G.E.C. Lamp Works and must not be communicated to any other person, nor reproduced, nor removed from the Company's premises without written authority.